Key City Plating Co.

2500 Kerper Blvd.

Dubuque, la 52001

Gary Witkovski

Neal Smith Federal Building

210 Walnut Street Room 473

Des Moines, la 50309-2109

ANNONEMM

Re; NOPF from inspection 5-22-17, by William F. Sparks

The storage drum used to collect dirty Xylene, was not sealed. One of the bung plugs was not sealed in place.

We sealed it when it was noticed by your inspector. Our employees have been informed to keep the bung plugs sealed tight when not adding to the drum.

The Xylene is to be recycled by Safety-Kleen. They have scheduled to pick it up on 5-31-17.

Richard Conlon (owner)

RCRA 06/02/2017



Key City Plating Company

2500 KERPER BLVD. DUBUQUE, IOWA 52001-1460 CEDAR RAPIDS IA 524
30 MAY 2017 PM 2 T